

**Error Code 21 (Indoor Models Only)**

Explanation: Air intake filter switch does not work. The air intake filter switch ensures the front cover is attached and the inlet filter screen is in place and clean. Air intake switch and Error Code 21 has been removed from second generation 4.2, 5.3 and all Direct Vent (DV) models. At a minimum check the following:

1. Make sure air filter door is properly seated and clean.
2. Make sure front panel is properly installed with all four retaining screws.
3. Press the air intake switch when operating the unit without the front cover installed.

